
Université de Liège

Hydro-mechanical behavior of Boom clay host-rock in interaction with a deep excavated gallery's lining

F. Salehnia¹, X.Sillen², X.L. Li³, R.Charlier¹



Department ArGEnCo, Université de Liège, Chemin des Chevreuils, 4000 Liège, Belgium
Belgian Agency for Nuclear Waste and Fissile Materials (ONDRAF/NIRAS), Avenue des arts 14, 1210 Brussels, Belgium
European Underground Research Infrastructure for Disposal of Nuclear Waste in Clay Environment (EIG EURIDICE), Mol, Belgium



Main References:

- Salehnia F, Collin, F, Li XL, Dizier, A, Sillen, X, Charlier, R. Coupled modeling of Excavation Damaged Zone in Boom clay: Strain localization in rock and distribution of Contact pressure on the gallery's lining. Comput. Geotech., 2015; 69:396-410. http://authors.elsevier.com/a/1RFBF,63b~XrRb
- Salehnia.F. From some obscurity to clarity in Boom clay behavior: Analysis of its hydro-mechanical response in the presence of strain localization.PhD thesis,Université de Liège2015 0032/43663790

Contact:

salehnia@ulg.ac.be

• Collin F, Chambon R, Charlier R. A finite element method for poro mechanical modelling of geotechnical problems using local second gradient models. IJNME, 2006;65(11):1749–72.